



# REPLACEMENT SHEET

ATTY DKT. No.: MRKS/0093  
U.S. SERIAL No.: 10/613,341  
FILED: JULY 3, 2003  
TITLE: COUPLING TUBULARS

CONF. No.: 5149

PAGE 2 of 4




FIG. 3




FIG. 4




FIG. 5

# REPLACEMENT SHEET

ATTY DKT. NO.: MRKS/0093

U.S. SERIAL NO.: 10/613,341

FILED: JULY 3, 2003

TITLE: COUPLING TUBULARS

CONF. NO.: 5149

PAGE 3 of 4

3/4




FIG. 6




FIG. 7




FIG. 8

# REPLACEMENT SHEET

ATTY DKT. No.: MRKS/0093  
U.S. SERIAL No.: 10/613,341  
FILED: JULY 3, 2003  
TITLE: COUPLING TUBULARS

CONF. No.: 5149

PAGE 4 of 4

4/4




FIG. 9